

**Fire & Safety Co**

18 Shipyard Way

Unit 4

Bay City, CT 06705

203-555-0148

office@fireandsafetyco.example

CT ELC.0198097

Kitchen Exhaust Cleaning Report

Property	Anchor Steakhouse	Date	9/23/2026
Address	55 Dockside Rd Bay City, CT 06705	Inspector	Luis Ortega
Customer	Anchor Restaurant Group		

Hoods (2)

Hood	Location	Result
Broiler hood	Kitchen, north wall	PASS
Range hood	Kitchen, west wall	PASS

Broiler hood, Kitchen, north wall

Suppression system: Ansul · Appliances, left to right: Charbroiler, 2-basket fryer, Salamander

Cleaning interval: Quarterly (NFPA 96) · Next cleaning due: 12/23/2026

GREASE DEPTH

Grease build-up on filters	None
Grease build-up in the hood	None
Grease build-up in the ductwork	None
Grease build-up on the fan	None
Grease build-up on the roof	None

EXHAUST SYSTEM INSPECTION

Exhaust hood captures all heat and cooking effluent	YES
Entire system interior is accessible	YES
Adequate access panels are provided	YES

Filters are conforming and in place	YES
Water wash hood is operational	YES
Hood damper operates properly	YES
Access is free of dangerous non-conforming conditions	YES
Fan is tippable or its interior is accessible	YES
Fan is working properly	YES
Fan wiring is free of defects	YES
Roof around the fan is free of grease build-up	YES
System is liquid tight	YES
Entire system is clean to applicable codes	YES

RECOMMENDATIONS & ACCESS

Recommended cleaning frequency	4 times per year
Next cleaning date	12/21/2026
Every area of the system was accessible and cleaned	YES
Areas not accessible or not cleaned	None. Full access to hood, plenum, duct and fan.
Photos or additional information attached	YES

Range hood, Kitchen, west wall

Suppression system: Ansul · Appliances, left to right: 6-burner range, Flat top griddle

Cleaning interval: Quarterly (NFPA 96) · Next cleaning due: 12/23/2026

GREASE DEPTH

Grease build-up on filters	None
Grease build-up in the hood	None
Grease build-up in the ductwork	None
Grease build-up on the fan	None
Grease build-up on the roof	None

EXHAUST SYSTEM INSPECTION

Exhaust hood captures all heat and cooking effluent	YES
---	-----

Entire system interior is accessible	YES
Adequate access panels are provided	YES
Filters are conforming and in place	YES
Water wash hood is operational	YES
Hood damper operates properly	YES
Access is free of dangerous non-conforming conditions	YES
Fan is tippable or its interior is accessible	YES
Fan is working properly	YES
Fan wiring is free of defects	YES
Roof around the fan is free of grease build-up	YES
System is liquid tight	YES
Entire system is clean to applicable codes	YES

RECOMMENDATIONS & ACCESS

Recommended cleaning frequency	4 times per year
Next cleaning date	12/21/2026
Every area of the system was accessible and cleaned	YES
Areas not accessible or not cleaned	None. Full access to hood, plenum, duct and fan.
Photos or additional information attached	YES

SIGNATURES



Inspector: Luis Ortega

Date: 9/23/2026

This inspection was performed in accordance with NFPA 96.